

The above represents a reference site plan with information from the 04/02/13 inspection where samples were taken. Corresponding photographs were taken at the KJMM1 sample site, temporary dam site, and the confluence of the unnamed tributary (drainage ditch) with Mud Creek. Red arrows show the direction of fresh water travel in the "Drainage Ditch" which is unnamed tributary draining storm water to Mud Creek shown on the west side of the map where blue arrows indicate the direction of creek flow. Black arrows show the direction of storm water drainage. Corners of the land application areas are the bulls eyes that were GPS documented on 04/02/13to provide reference to the application area. Sample locations from the 04/02/13 inspection are shown with bulls' eyes and orange indicators. An upstream sample of Mud Creek was taken on 04/02/13 where the blue indicator identifies the bulls' eye on the map. No samples were taken at the time of inspection on 4/25/13 as cleanup appeared complete and no discharge was occurring.